## Firmware Update history

-----

## [Feb 2025]

- 1.6.0 Added Input Level Trim control (in Options menu).
  - Fixed intermittent USB disconnection.
  - Calling the same preset as the one currently used will now restore the state as was saved in the preset.
  - Fixed crackling noises that appear in some algorithms when the input signal level is high.

## [Jan 2025]

- 1.5.0 Fixed tempo glitch during preset change with midi clock active.
  - Fixed tempo glitch when delay time is set close to 60ms for certain delay and reverb algorithms.
  - Fixed 'Predelay' parameter bug in Chamber algorithm.
  - Fixed 'Voice Intensity' parameter in Spatium algorithm.
  - Fixed Crinkle parameter bug in Tape Delay algorithm.
  - Fixed Dry Level control bug in Dual Mono routing.
  - Changed the wording for MIDI Out Pin selection from 'Tip Active' to 'Type-A (standard)', and 'Ring Active' to 'Type-B'.
  - Improved operational stability.

## [Jan 2025]

- 1.4.0 Added Bank-Change display option in Global settings.
  - Added Looper volume control via MIDI.
  - Added Sum-to-Mono control via MIDI.
  - Fixed 'Crinkle' parameter issue in Tape algorithm.
  - Fixed looper audio freezing issue.
  - Fixed an issue where certain global configurations are not working.

#### [Dec 2024]

1.3.1 - Fixed 'Crinkle' parameter behavior in Tape algorithm.

## [Dec 2024]

- 1.3.0 Fixed preset save issues.
  - Fixed incorrect tempo bug when switching presets.

### [Dec 2024]

- 1.2.0 Added interfacing with the SV Studio editor software.
  - Added 'Auto Ramping' function.
  - Added MIDI-CC commands for Auto Ramping functions.
  - Added MIDI-CC commands for Bank Scroll function.
  - Added Looper operation capability via Aux switches.
  - Added Looper operation capability via MIDI.
  - Added 'Aux Switch Theme' to Global Settings.
  - Fixed MIDI clock reception issue.
  - Fixed incorrect parameter labels for Dual D2D delay.
  - Fixed incorrect LED update on X side when changing preset.
  - Fixed tempo LED flashing bug.

# [Nov 2024]

- 1.0.1 Improved footswitches handling robustness.
  Fixed bug with tap-tempo operation via Aux switch.
  Fixed bug with CC#4 / CC#21 when used with reverbs.
  - Improved looper operation stability.

# [Oct 2024]

1.0.0 - First release firmware.