

## Firmware Update history

-----  
[Jan 2025]

- 1.4.0 - Added Bank-Change display option in Global settings.
  - Added Looper volume control via MIDI.
  - Added Sum-to-Mono control via MIDI.
  - Fixed 'Crinkle' parameter issue in Tape algorithm.
  - Fixed looper audio freezing issue.
  - Fixed an issue where certain global configurations are not working.

[Dec 2024]

- 1.3.1 - Fixed 'Crinkle' parameter behavior in Tape algorithm.

[Dec 2024]

- 1.3.0 - Fixed preset save issues.
  - Fixed incorrect tempo bug when switching presets.

[Dec 2024]

- 1.2.0 - Added interfacing with the SV Studio editor software.
  - Added 'Auto Ramping' function.
  - Added MIDI-CC commands for Auto Ramping functions.
  - Added MIDI-CC commands for Bank Scroll function.
  - Added Looper operation capability via Aux switches.
  - Added Looper operation capability via MIDI.
  - Added 'Aux Switch Theme' to Global Settings.
  - Fixed MIDI clock reception issue.
  - Fixed incorrect parameter labels for Dual D2D delay.
  - Fixed incorrect LED update on X side when changing preset.
  - Fixed tempo LED flashing bug.

[Nov 2024]

- 1.0.1 - Improved footswitches handling robustness.
  - Fixed bug with tap-tempo operation via Aux switch.
  - Fixed bug with CC#4 / CC#21 when used with reverbs.
  - Improved looper operation stability.

[Oct 2024]

- 1.0.0 - First release firmware.