

Firmware Update history

[Dec 2024]

1.3.1 - Fixed 'Crinkle' parameter behavior in Tape algorithm.

[Dec 2024]

1.3.0 - Fixed preset save issues.

- Fixed incorrect tempo bug when switching presets.

[Dec 2024]

1.2.0 - Added interfacing with the SV Studio editor software.

- Added 'Auto Ramping' function.
- Added MIDI-CC commands for Auto Ramping functions.
- Added MIDI-CC commands for Bank Scroll function.
- Added Looper operation capability via Aux switches.
- Added Looper operation capability via MIDI.
- Added 'Aux Switch Theme' to Global Settings.
- Fixed MIDI clock reception issue.
- Fixed incorrect parameter labels for Dual D2D delay.
- Fixed incorrect LED update on X side when changing preset.
- Fixed tempo LED flashing bug.

[Nov 2024]

1.0.1 - Improved footswitches handling robustness.

- Fixed bug with tap-tempo operation via Aux switch.
- Fixed bug with CC#4 / CC#21 when used with reverbs.
- Improved looper operation stability.

[Oct 2024]

1.0.0 - First release firmware.